
VASA NASA

- 1 Forward Chassis
- 2 Mobility Subsystems
- 3 Crew Station
- 4 Aft Pallet

Lunar Dust Protection for Apollo Rover Mechanisms

Ron Creel - Lead for LSIC Dust Mitigation "Isolation Technologies" Subgroup



Kevlar Shield to Protect Rover from LM Lander Stirred Up Dust

1 - Forward Chassis Dust Protection





Lunar Dust Brush



Astronaut Brushing Dust from LRV Thermal Radiators

Misleading Pre-Apollo 15 <u>Earth TVAC Testing</u> at the Manned Spacecraft Center, Using Apollo 12 Soil and Much Higher Pressure (10⁻⁶ Torr), Predicted Brushing Could Be Used on the Moon to Effectively Clean Thermal Control Surfaces and Crew Suits

Extensive Dust Cleaning Regrettably Did NOT Work on the Moon with Much Lower Environmental Pressure of 10⁻¹² Torr

Right Rear Fender Extensions Knocked Off on Apollo 16 and 17




Post Mission - LRV Mission Support


Team Presented Signed Fender


Extension to the Apollo 17 Crew

2 - Mobility Subsystems Dust Protection










roving.ron@gmail.com

3 - Crew Station Dust Protection




Commander Cernan Indicated that a 4th EVA was Not Possible Due to Dust Getting into Aft Pallet Swing Arm Hinges and Other Mechanisms


Lunar Module Pilot Schmitt encountered some difficulty in operating the Sun Shade of the Lunar Extravehicular Visor Assembly because of <u>lunar dust in the slide mechanism</u>





KC-135 Testing Required for "1/6 G" Seatbelt Redesign

Sample Return Container Seals Were Also Compromised on All LRV Missions











THE PART N.	CONTR. NO.	O MODELL MIND	THE DASH NU	LECTO	TAUCC
DIMENSIONS ARE IN INCHES TOLERANCES ON	OFTENN GEZELIUS	2-70	-DEFENSE	RESEARCH LAR	JIVIL'S SORATORIES
PLACE 3 PLACE ANGLES DECIMALS DECIMALS ±.03 ±.0/0±—	ENGR 5 Z	-17-7 ₀ TITLE		007,	
MATERIAL SILICONE RUBBER PER 7552884-001	APPO William	62/2 DL		D MOISTU	
REF (AC-DRL) CHC CONTROL	OTHER APPROVAL		13160 E 2// WEIG	75532	88 A






- Aft Pallet Dust Protection (Limited)


Swing Arm Hinges Failed to Close on All 3 Rovers after 3 EVAs





Geological Tools on Apollo 17
Aft Pallet

Surface Electrical Properties (SEP) Antenna




SEP receiver. The receiver is mounted on the rear of the Rover. Data, measured while the Rover moves along a traverse, are also recorded automatically on a cassette tape recorder.

SEP Receiver Mounted on Apollo 17 Aft Pallet Front Side

roving.ron@gmail.com

Questions?



roving.ron@gmail.com